

Manhole Inspection Summary

Manhole # S35YY_027MH

Printed On: 12/17/2008

Page 1 of 3

Inspection Is Incomplete Rating: **3) Fair**

Record Plat: **35YY** Node: **027** Status: **Found**

Insp Date: **12/22/06 11:24 AM**

Incomplete Comments

Crew: **JS, DE**
Inspector: **Smutek, J**
Firm: **REI**

Location Address: **107 32ND ST**

Cross Street: **CALVERT ST**

Manhole Type: **Inline** Location: **Sidewalk** Ground Conditions: **Wet**

Prev. Rehab Weather: **Dry** Subject To Ponding: **None**

Comments

Cover Shape: **Circular** Diameter: **24** (in.) Length: (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: Bolted Vented Water Tight Water Tight Insert

Frame Offset: **4** (in.) Condition: Sound Cracked **Leaks**

Chimney / Frame Adjustment Exists Material: **Brick** Parged Height: **3** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick **Deteriorated**

Infiltration: None **Joint** Cracks Mortar Roots **Wall**

Corbel Material: **Brick** Parged Type: **Concentric/Eccentric**

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Barrel Material: **Brick** Parged

Shape: **Circular** Diameter: **46** (in.) Length: (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Bench Exists Material: **Brick** Parged **Debris** (not Condition related)

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Channel Material: **Brick** Parged Debris (not Condition related)

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth:

Condition: Sound Cracked Root Intrusion Deteriorated Leaks **Debris**

Steps Count: **2** Missing: **0** **Corroded**

Surcharge **Evidence Of Surcharge** Depth: **1** (ft.) Active Surcharge Present

Location View



Top View



Corroded steps. Evidence of surcharge - Bench debris. Channel debris.

Defect



Frame leaks. Frame offset. Adjustment deterioration and infiltration.

Manhole Inspection Summary

Manhole # S35YY_027MH

Printed On: 12/17/2008

Page 3 of 3

8 in. Circular Gravity Sewer Pipe Out @ 12 O'Clock



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **5.89** (ft.) Flow Characteristics: **None**

Deposits: None **Mud** Sludge **Debris** **Grease**

Silt Depth: **0** (in.) Deposits Extent: **Light**

Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection

8 in. Circular Gravity Sewer Pipe In @ 6 O'Clock



Rod and Bar (Angled)

Pipe Material: **Clay** Pipe Lined

Invert Depth: **5.65** (ft.) Flow Characteristics: **None**

Deposits: None **Mud** Sludge **Debris** Grease

Silt Depth: **0** (in.) Deposits Extent: **Light**

Infiltration: **None** Pipe Seal Cond: **Unknown**

Drop: **None**

Connects To: **Manhole**

Possible Illicit Connection